

Non-Domestic Gas Safety Record

Certificate Reference

Saint Andrews Place 2019

cedure

Certificate No:50016

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure

No detailed internal inspection of flues (integrity, Construction and Lining) has been carried out

| Engineers Details | | | | | | | | Instal | Installation Details | | | | | | | Client Details | | | | | | |
|---|---|--|----------------|----------|----------|-------|------|---------------|----------------------|-----------------------------------|---------------------------------------|--|-----------------------------|--------------------------------------|--------------------|---|--|---|---|--------------------------------------|--------------------------------------|--|
| Trading Title Address | | Mutch Heating Engineers 102 Upton Rd Moreton Wirral Post Code: CH460SF | | | | | | Insta Addr | llation ess | St Andrews Place Rodney Street | | | | | | Client Addres | | Property Sh House | ор | | | |
| | | | | | | | | | | Liverpool | | | | | | | 24a I | 24a Hatton Garden Liverpool | | | | |
| | | | | | | | | | | Post Code: | | | | L19ED | L19ED | | | i | Post Co | ost Code: L32AN | | |
| | s Safe No: | 503741 Telephone No: 07525207430 | | | | | Tele | phone N | lo: | | | | | Telephone | | | | | | | | |
| Appliance Details | | | | | | | | | | Inspection Details | | | | | | | <u> </u> | | | | | |
| | Locati | on | Appliance Type | Make | | Model | | CO2 Reading | CO Reading | FlueType (OF/RS/FL) | Appliance Inspected (YES/NO/NA) | Combustion Analysis Reading (CO/CO2) | Operating Pressure(mbar) | Lanlords Appliance (Yes/No/NA) | Heat Input (kw) | Safety Device(s) Correct Operation (Yes/No/NA) | Ventilation Provision Satisfactory (Yes/No) | Visual Condition of Flue and Termination Satisfactory (Yes/No/NA) | Flue Performance Test) (Pass/Fail/NA) | Appliance Serviced (Yes/No/NA) | Appliance Safe To Use (Yes/No) | |
| 1 | Boiler Room | piler Room System | | Veissman | Veissman | | | 7.9 | 17 | RS | YES | 0.0002 | | YES | 100 | YES | YES | YES | PASS | NO | YES | |
| 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | | | |
| Faults/Notes | | | | | | | | | | Remedial Work Taken | | | | | | | Warn | Warning Notice Fixed | | | | |
| 1 | | | | | | | | | | | | | | | | | | | | | | |
| 2 | 2 | | | | | | | | | | | | | | | | | | | | | |
| 3 | 3 | | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | | | |
| YES das rightness satisfactory. YES | | | | | | | | | nature | atures Gas ID Number: | | | | | | | | | 3669171 | | | |
| Gas Installation Pipework Visual Inspection Satisfactory: YES Nam | | | | | | | | | | | | | | | | | Thu-02-05-2019 | | | | | |
| Number Of Appliances Tested: 1 Equipotential Bonding: YES Repo | | | | | | | | | | | t Received By: | | | | | | | | | | | |
| | NEXT INSPECTION DUE ON Fri-01-05-2020 Installation Pass: NA Nam | | | | | | | | | Signed: | | | | | | | Thu-0 | Thu-02-05-2019 | | | | |